























NO.	S/N	RAM CONFIG	LOCATION	REMARK	PHOTO	ID PHOTO
1	DTVWNS064314001	2/2	POS5			
2	DTVWNS064314002	1/2	RECEIVING	SPARE		





3	DTVWNS064314003	2/2	EXPRESS COUNTER			
4	DTVWNS064314004	2/2	POS2			





5	DTVWNS064314005	2/2	LABEL PRINTER			
6	DTVWNS064314006	2/2	POS4			



7	DTVWNS064314007	2/2	POS3			
8	DTVWNS064314008	2/2	OFFICE			

9	DTVWNS064314009	2/2	OFFICE			
10	DTVWNS064314010	2/2	OFFICE			

11	DTVWNSM002308044719600	2/2	OFFICE			
12	DTVWNSM002308044419600	2/2	RECEIVING			

13	DTVWNM0023080447A9600	2/2	RECEIVING			
14	DTVWNM002308044699600	1/2	CASH ROOM	SPARE		

15	DTVWNSM002308044279600	2/2	CASH ROOM			
16	DTVWNSM002308044619600	1/2	NADA'S OFFICE			

17	DTVWNSM0022380270E9600	2/2	POS1		
----	------------------------	-----	------	---	---

Total number of PC Audited: 17
Total number of RAM sticks found in PC: 31

Audit Performed by, Verified by,

Name: _____
Position: _____

Supervised by,

Name: _____
Position: _____

Name: _____
Position: _____